



TRAIL ACCESS INFORMATION



Hiking



Biking



Pets on Leash



Horseback Riding



Cross Country Skiing



No Motorized Vehicles



Kiosk at Potter Rd. Trailhead

Funded by:



thelastgreenvalley.org
DEEP Rec Trails Program

CT Air Line State Park Estabrooks Road west to Potter Road

Hampton, CT • Linear Trail - There are no fees for visiting the trail

Length	1.5 mi (2.3 km)
Elev Gain	24.2 ft (7.4 m)
Elev Loss	88.7 ft (27 m)

Trail Entrance & Parking

Directions to Estabrooks Road, Hampton CT

From Route 6 and route 97 intersection, follow Route 97 north for 2 miles, take a slight left onto Station Rd., continue for 0.5 miles, turn left onto Estabrooks Rd. follow for 1.2 miles.

Parking: No official parking area. On the west side of the road, there is room for 4-5 cars to park in a line parallel to the ramp.

Directions to Potter Road, Hampton CT

From Route 6 and Route 97 intersection, follow Route 6 west 1.4 miles, turn right onto Potter Rd. Large Parking is available on Potter Road 0.6 miles north of its intersection with Route 6 at Goodwin Conservation & Nature Center. Parking area is about 0.25 miles south from Air Line Trail.

Parking: There is no official parking for the trail at this road crossing, however, 2-4 cars can park along the road.

DO NOT BLOCK GATES.



Grade

Typical Grade	1.5%
1% (80 ft) of trail is	6% -10%
ADA Maximum Ramp Grade	8.3%



Cross Slope

Typical Cross Slope	3%
6.8% (528 ft) of trail is	6% -10%



Tread Width

Typical	95 in
Minimum	0.02% (2 ft) 20 in



Surface

Surface Type	Aggregate/Gravel
0.3% (23 ft) of trail is	Paved
99.2% (7631 ft) of trail is	Firm
0.5% (49 ft) of trail is	Soft



Obstructions

ACCESS GATE AT ESTABROOKS ROAD is locked and footpath at left side of west gate is narrow 30 in. with a rock in path.

ACCESS GATE AT POTTER ROAD is locked and footpath at right side of east gate is narrow 20 in.

ACCESS GATE AT POTTER ROAD is locked and footpath at left side of west gate is 43 in.

WARNING: Trail conditions may have changed since May 2017 when this trail was assessed. Temporary obstacles were not mapped.

OBSTRUCTIONS: Obstructions less than 2 in (5 cm) were not measured.